U-Blox Receiver COM Port Setting

Dinesh Manandhar

Center for Spatial Information Science

The University of Tokyo

Contact Information: dinesh@iis.u-Tokyo.ac.jp



Run Device Manager
You will see SENSORS – u-blox GNSS Location Sensor
If your receiver doesn't work with this setting, update this driver



Click Mouse Right Button

Select this option



Dinesh Manandhar, CSIS, The University of Tokyo, dinesh@iis.u-tokyo.ac.jp

Select this option



Dinesh Manandhar, CSIS, The University of Tokyo, dinesh@iis.u-tokyo.ac.jp

Select this option



Dinesh Manandhar, CSIS, The University of Tokyo, dinesh@iis.u-tokyo.ac.jp



A new COM Port will be installed

Next, Remove usb cable and re-connect once again. You should see the same COM port

Run u-center and select COM Port. You will see the New COM port here. Select it.

It should work now See the COM Port and green light blinking here